



## Devil's Slide/Hwy 1 Storm Repair

Daily Updates from Bijan Sartipi



**Daily Update**  
July 10

### Repair Work

Devil's Slide (post mile 39.14)

- Level 'B' (lower level ocean side) – Drilling for tie backs continued using the reach over rig. 53 of 58 tie backs now installed. Tie back stressing also continued.



Drilling at level B with reach over rig

- Level 'C' (lower level cliff side) – Tie back stressing was completed today.
- Level 'D' (upper level cliff side) – Drilling for tie backs continued today from the temporary bench. 22 of 33 now installed.



Drilling at level D

## Retaining (micropile) Wall

- Drilling and driving steel piles continued today. 39 of 99 now installed.



Cement mixing for the micropile wall operation

## Information Signs

- The following signs were installed last weekend.



Junction of highways 1 and 92



NB Hwy 1 near south road closure point